

IMPORTANT NOTICE

Beginning in mid-1988, GM double-sided ignitions were fitted with wafers having a relief notch. You will achieve greater success in picking these locks if, when inserting the pick, you angle it counter-clockwise as shown in the illustration. This method prevents the pick from falling into the relief notches as you actuate the wafers through 'rocking'.

